

M35080V6 Eraser/Programmer ERRATA

Make sure, that m35080V6 software installed on the system disk (disk C for most cases). Otherwise start m35080V6.exe program from the software folder to avoid error message:



Figure 1.

Animation files must be located in the same folder. Necessary files for the software folder:

1. St6ust.log.....unistall service file
2. m35080V6.exe.....control software file
3. English.lpk.....configuration file
4. pic00.jpg.....animation file
5. pic11.jpg.....animation file
6. pic22.jpg.....animation file
7. pic33.jpg.....animation file




Figure 2.