


ST92F Flash / E3PROM ISP Programmer




Errata

November 2013



Microcontroller-Cafe



Checkpoint Lab

ST92F FLASH/E3PROM ISP Programmer

If your PC Hardware is not compatible with the i16650/i16640 program model, the autodetection will not work. For this case use manual selection of the serial port to begin working with the ST92FXXX E3PROM Programmer.

